

Applicable to following products: All components made from cherry wood (doors, windows, moldings, panels, etc.)

MINERAL STREAKS AND DARK LINES IN CHERRY WOOD

Purpose of the Bulletin

This bulletin is intended to clarify that the appearance of dark streaks or lines—commonly referred to as mineral streaks—is a natural characteristic of cherry wood. These markings are not considered defects. On the contrary, they contribute to the unique beauty of cherry wood and have no impact on the structural integrity or performance of our products.



What Causes These Marks ?

- **Natural process:** These dark lines result from mineral deposits or resins absorbed by the tree over time.
- **Unique visual features:** Their location and appearance vary from piece to piece, making each cherry wood component truly one of a kind.

Typical (and Acceptable) Characteristics

Feature	Natural Characteristic
Color	Dark brown or black streaks within the grain
Texture	Smooth surface, free of cracks or indentations
Pattern	Random but stable grain variations